

# Alarm description document

The document describes Appear TV platform alarms

Doc. Name : Alarm description document  
Revision : 3.40  
Date : 29/09/2020

## Table of Contents

1	ADM	3
2	Configuration	5
3	DDM	6
4	DDMDESCR	8
5	DESCRCI	9
6	Demodulation	10
7	ECMG	11
8	EIS	13
9	EMMG/PDG	15
10	EPG	17
11	Encoding	18
12	Encryption	21
13	License	23
14	Maintenance	24
15	Modulation	25
16	Monitoring	26
17	Network	27
18	PSI	28
19	PSIREGEN	29
20	Radio	30
21	Redundancy	31
22	Statmux	33
23	Stream	34
24	System	36
25	Upgrade	39

## 1 ADM

Error Code	ID	Level	Description
FPGA TS packet overflow.	327680	critical	The FPGA has run out of TS packet buffer. TS packets are being discarded. (ADM)
Transport stream missing	327681	critical	The decoder has not received any TS packets the last second. (ADM)
High Continuity Error Rate	327682	critical	Input stream error detected. (ADM)
Stream Continuity Error	327683	warning	The CC has been changed non-incrementally. Most likely due to network issues. (ADM)
PCR PID Missing	327684	warning	Missing PCR PID. (ADM)
PCR Missing	327685	warning	No PCR in PCR PID. (ADM)
Video PID Missing	327686	critical	No TS packed associated with this PID has been received by the decoder the last second. (ADM)
Video PID Scrambled(ADM)	327687	critical	Video PID received by decoder is scrambled. Check de-scrambling (CAM and Smartcard). (ADM)
Video Missing	327688	major	No video data in the TS packed identified by the Video PID. (ADM)
Video Data Error	327689	major	The decoder found errors in the decoded video. (ADM)
Audio PID Missing	327690	critical	No TS packed with this PID has been received by the decoder the last second. (ADM)
Audio PID Scrambled	327691	critical	The audio PID is scrambled. (ADM)
Audio Frames missing	327692	major	The decoder has not decoded Audio the last second. May be due to no audio in the Audio PID. (ADM)
Audio Data Error	327693	major	The decoder found errors in the decoded audio. (ADM)
Audio Output PCM underflow	327694	major	Audio buffer is running low. Signal error. Try to tune a different source to exclude system error. (ADM)
VBI No valid data	327701	warning	Unusable Vertical Blanking Interval data.. (ADM)
VBI-data missing	327702	warning	Missing Vertical Blanking Interval data. (ADM)
AFD-data missing	327703	warning	The decoder has been configured to enable WSS-AFD, but does not receive any WSS AFD data. (ADM)
DVB Subtitles LQ/ERROR	327704	warning	The DVB subtitling contains errors which will lead to low quality DVB subtitles or no subtitling at all. (ADM)
Bad backplane frame	327713	major	Communication error with backplane. (ADM)
Video sync turned off	327714	notify	Video sync turned off due to other alarm (configurable). (ADM)
CAM Reset by operator(ADM)	327715	notify	Notification that the user has reset the CAM through the GUI. (ADM)
Message sent by CAM (ADM)	327718	notify	The CAM sends an informational message. (ADM)
Teletext data overflow	327719	warning	Unable to place all Teletext lines. There are teletext data for more lines than available for teletext in the VBI. (ADM)
License Violation: HD-decoding	327720	warning	Missing HD-decoding license, but trying to decode HD stream. (ADM)
Invalid parameter received	327721	warning	One or more parameters in the configuration are outside the valid range. The complete configuration is discarded. There is probably a mismatch between MMI SW and ADM SW. (ADM)

Error Code	ID	Level	Description
Audio Decoder Failed	327722	critical	The audio decoder is unable to decode the current audio stream format. Card needs to be rebooted. (ADM)
Closed caption missing	327723	warning	Closed caption enabled but missing. (ADM)
PCR Regulation overflow	327724	warning	Regulation beyond recommended level. (ADM)
PCR Jitter Too High	327725	warning	Higher than recommended PCR jitter. (ADM)
HD Decoder not available	327726	critical	HD Decoder already used. (ADM)
No space for service info vanc packet	327727	warning	No space for service info in vertical ancillary data. (ADM)
No space for op47 vanc packets	327728	warning	No space for OP-47 in vertical ancillary data. (ADM)
No space for cc vanc packet	327729	warning	No space for closed captioning in vertical ancillary data. (ADM)
Black picture	327730	major	Black picture detected. (ADM)
Frozen picture	327731	major	Frozen picture detected. (ADM)
Card Logout	327733	critical	No contact with login daemon. (ADM)
Genlock Failure: No lock on input reference	327734	major	ADM not able to lock to reference signal. (ADM)
No space for smpte2031 vanc packet	327735	warning	No space for smpte in vertical ancillary data. (ADM)
No space for dpi vanc packets	327736	warning	No space for dpi in vertical ancillary data. (ADM)
Switched, reason: Logout	327752	notify	The internal redundancy module switched to the other input card because it lost contact with the login server on the MMI board. (ADM)
Switched, reason: No bitrate(ADM)	327753	notify	The internal redundancy module switched to the other input card due no bitrate on the backplane. (ADM)
Switched, reason: Operator	327754	notify	The internal redundancy module switched to the other input card due to a command from the user. (ADM)
RF Upconverter no lock	3604496	critical	PLL on upconverter is not locked. Indicates HW error. (ADM)
RF overheated	3604497	critical	Temperature on RF module is too high. Check the position of the air flow vent in the lower part of the chassis. (ADM)
RF Externally Muted	3604498	warning	The RF is muted by an external device via the mute interface. (ADM)
RF Output Low Power Level	3604499	critical	RF Output Power is below expected level. (ADM)
SW/HW mismatch	3604509	major	The HW platform is used for different card types. If there is a mismatch between the option set and the software used, the alarm is called. (ADM)
RF configured to continuous wave	3604517	warning	Test signal with an unmodulated carrier, no picture or audio. (ADM)
RF muted by Alarm RF Control	3604532	warning	RF output is muted. (ADM)

## 2 Configuration

Error Code	ID	Level	Description
FPGA mismatch	1048610	critical	Wrong FPGA is used. No configuration possible. Please upgrade.
Number of data source inputs exceeded	1048642	warning	The maximum number of data source routings is 64 and the combined number of inputs (monitor only) and routed inputs exceeds this number. Contact support for more information.
Invalid parameter	1048650	critical	Configuration rejected.
Card misconfiguration of default backplane.	2621498	critical	The XC5100 1RU chassis does not accept cards configured to log in to the MMI via backplane 2. Use atvcardssetup to correctly configure the card.
IP addresses reset to default values due to HW switch set	3080197	critical	The DIP switch resetting the IP address to its default value, 192.168.1.100, is active.
Card setup changes detected: Reboot to complete	3080297	critical	Some cardsetup changes require a card reboot, as the setting used during boot.
Missing expected node in configuration XML file	3080307	warning	This alarm indicates the configuration sent to the card does not contain the required xml tags. Make sure that the unit is running correct software versions.
Invalid configuration	3997709	major	Invalid parameter in card config.
Port configuration failed	4390935	critical	Invalid parameter.
Error building card configuration	5046273	critical	Error encountered in building a card's configuration. The configuration for the specified slot and module is outdated.
Interfaces exhausted	5046274	critical	The specified service is not routed through the unit, because all input or output interfaces on the specified slot and module are in use. In other words, too many streams are configured through this module. The user should generally be prohibited from adding too many streams, except accounting for certain dynamic features like Autoservice, in which the number of resulting streams is unpredictable at configuration time.
Illegal interface	5046275	critical	The specified service is not routed through the unit, as result of internal misconfiguration. Undoing the non-working configuration should help.
Pid clash	5046276	critical	Two or more muxed components are using the same PID. The output data on this PID is corrupted. Please check your configuration, including the output port's PID mapping and settings for reserved PSI PIDs.
Illegal stream definition	5046277	critical	A configured stream with the given database ID is invalid. Please contact support for assistance. The stream ID is NOT visible in the GUI.
Unable to configure statmux group	5046278	critical	System is unable to effectuate a statmux (V2) group configuration with the available hardware. There must be at least one coder per statmux group, not counting N+M redundancy spares.
Invalid configuration.	5177344	major	The card configuration contains invalid settings. Try to revert latest configuration changes.
No timecode set	5177382	major	The multiscreen transcoded service is set in manual timecode mode, but no timecode was found.

### 3 DDM

Error Code	ID	Level	Description
FPGA TS packet overflow	131072	critical	The FPGA has run out of TS packet buffer. TS packets are being discarded. (DDM)
Transport stream missing	131073	critical	The decoder has not received any TS packets the last second. (DDM)
High Continuity Error Rate	131074	critical	Input stream error detected. (DDM)
Stream Continuity Error	131075	warning	The CC has been changed non-incrementally. Most likely due to network issues. (DDM)
PCR PID Missing	131076	warning	No TS packed associated with this PID has been received by the decoder the last second. (DDM)
No PCR on PCR PID	131077	warning	There is no PCR signaled on the PCR PID. (DDM)
Video PID Missing	131078	critical	No TS packed associated with this PID has been received by the decoder the last second. (DDM)
Video PID Scrambled	131079	critical	Video PID received by decoder is scrambled. Check de-scrambling (CAM and Smartcard). (DDM)
Video Missing	131080	major	No video data in the TS packed identified by the Video PID. (DDM)
Video Data Error	131081	major	The decoder found errors in the decoded video. (DDM)
PTS synch error	131082	major	PTS (Presentation TimeStamp) is unsynchronized versus the decoded pictures. (DDM)
Audio PID Missing	131083	critical	No TS packed with this PID has been received by the decoder the last second. (DDM)
Audio PID Scrambled	131084	critical	The audio PID is scrambled. (DDM)
Audio Frames missing	131085	major	The decoder has not decoded Audio the last second. May be due to no audio in the Audio PID. (DDM)
Audio Data Error	131086	major	The decoder found errors in the decoded audio. (DDM)
Audio Output PCM underflow	131087	major	Audio buffer is running low. Signal error. Try to tune a different source to exclude system error. (DDM)
RF Modulator No Lock	131088	critical	PLL on RF modulator is not locked. Indicates HW error. (DDM)
RF Upconverter no lock	131089	critical	PLL on upconverter is not locked. Indicates HW error. (DDM)
RF overheated	131090	critical	Temperature on RF module is too high. Check the position of the air flow vent in the lower part of the chassis. (DDM)
RF Externally Muted	131091	warning	The RF is muted by an external device via the mute interface. (DDM)
RF Output Low Power Level	131092	critical	RF Output Power is below expected level. (DDM)
Software download in progress	131093	notify	Software is being downloaded to the specified decoder. (DDM)
VBI PID Missing	131094	warning	No TS packed associated with this PID has been received by the decoder the last second. (DDM)
VBI No valid data	131095	warning	The data received on the VBI PID is not valid VBI data. (DDM)
VBI-data missing	131096	warning	(DDM)
AFD-data missing	131097	warning	The decoder has been configured to enable WSS-AFD, but does not receive any WSS AFD data. (DDM)



Error Code	ID	Level	Description
DVB Subtitles LQ/ERROR	131098	warning	The DVB subtitling contains errors which will lead to low quality DVB subtitles or no subtitling at all. (DDM)
RF Board mismatch	131101	warning	The decoder is configured with an option file that specifies that a RF board shall be present, but no RF board is detected. (DDM)
Nicam board mismatch	131102	warning	The decoder is configured with an option file that specifies that a Nicam board shall be present, but no Nicam board is detected. (DDM)
Common IF board mismatch	131103	warning	The decoder is configured with an option file that specifies that the decoder shall have Common Interface support, but no Common Interface hardware is detected. This is not related to the CAM itself. (DDM)
SW/HW mismatch	131104	major	The HW platform used by the decoder is also used for the Descrambler and Scrambler cards. During boot an option file is scanned which tells the card what it is. If the card is told it is a descrambler, but detects that it is the decoder software running then this SW/HW mismatch alarm is raised. (DDM)
A2 board mismatch	131105	warning	The decoder is configured with an option file that specifies that a A2 board shall be present, but no A2 board is detected. (DDM)
No Latens SSM	131106	warning	Missing Latens SW. (DDM)
Bad backplane frame	131112	major	Communication error with backplane. (DDM)
Video sync turned off	131114	notify	Video sync turned off due to other alarm (configurable). (DDM)
Switched, reason: Link Down	131115	notify	The internal redundancy module switched to the other input card due to a LINK DOWN condition on the backplane. (DDM)
Switched, reason: Logout	131116	notify	The internal redundancy module switched to the other input card because it lost contact with the login server on the MMI board. (DDM)
Switched, reason: Alarm	131117	notify	The internal redundancy module switched to the other input card due to an alarm condition on the DDM card. (DDM)
Switched, reason: Operator	131118	notify	The internal redundancy module switched to the other input card due to a command from the user. (DDM)
CAM Reset by operator(DDM)	131119	notify	Notification that the user has reset the CAM through the GUI. (DDM)
TS input rate too high	131120	warning	Input rate is higher than the configured output rate. (DDM)
RF configured to continuous wave	131121	warning	Test signal with an unmodulated carrier, no picture or audio. (DDM)
Message sent by CAM(DDM)	131122	notify	The CAM sends an informational message. (DDM)
Teletext data overflow	131123	warning	Teletext exceeds available VBI line space. (DDM)
License Violation: OSDM	131124	warning	OSDM feature used without license. (DDM)
License Violation: Stereo	131125	warning	Stereo feature used without license. (DDM)

## 4 DDMDESCR

Error Code	ID	Level	Description
FPGA TS packet overflow	196608	warning	Buffer overflow into the Descrambler card. Try to reduce the bitrate.
Software download in progress	196629	warning	Software is being downloaded to the specified descrambler.
OPTIONS DSCR SW/HW mismatch	196640	warning	The HW platform used by the descrambler is also used for the Decoder and Scrambler cards. During boot an option file is scanned which tells the card what it is. If the card is told it is a decoder, but detects that it is the descrambler software running then this SW/HW mismatch alarm is raised.
Component map overflow	196644	warning	The number of PIDs mapped through the Descrambler has exceeded the capacity of the card. Try to remove some service PIDs.
No CAM	196645	warning	CAM module is missing or not responding.
CAM communication error	196646	warning	Error in communication with CAM module. Currently not in use.
Descrambling failure	196647	warning	Buffer overflow into the Descrambler card. Try to reduce the bitrate.
Bad backplane frame	196648	warning	Data received were corrupt from the backplane. If this happens in large number hardware should be investigated.
CAM Reset by operator	196655	warning	The CAM module has been reset by the operator.
TS input rate too high	196656	warning	Input rate is higher than configured output rate.
Message sent by CAM	196658	warning	The CAM module sends an informational message.



## 5 DESCRCI

Error Code	ID	Level	Description
FPGA TS packet overflow	5570560	warning	Buffer overflow into the Descrambler card. Try to reduce the bitrate.
No CAM	5570590	warning	CAM module is missing or not responding.
CAM communication error	5570591	warning	Error in communication with CAM module. Currently not in use.
Descrambling failure	5570592	warning	Buffer overflow into the Descrambler card. Try to reduce the bitrate.
CAM Reset by operator	5570595	warning	The CAM module has been reset by the operator.
Message sent by CAM	5570598	warning	The CAM module sends an informational message.
Invalid parameter received	5570601	warning	One or more parameters in the configuration are outside the valid range. The complete configuration is discarded. There is probably a mismatch between MMI SW and Descrambler-CI SW.

## 6 Demodulation

Error Code	ID	Level	Description
No clock sync, T2MI streams stopped	1048615	critical	Lost clock sync. Muting outputs because the estimated time is not precise enough.
DVB-S derandomization failure occurred	1048616	critical	The receiver is unable to parse the received signal, check your PLS settings.
J.183/JCTEA format mismatch	1048646	warning	<p>The output frequency J.183/JCTEA setting does not match the corresponding input stream format.</p> <p>The reasons could be either:</p> <p>1) J.183/JCTEA is not enabled for the listed output frequency, but the corresponding input stream is in J.183/JCTEA format. (Message: Unexpected J.183/JCTEA format on Frequency 'id')</p> <p>2) J.183/JCTEA is enabled for the listed output frequency, but the corresponding input stream is not in J.183/JCTEA format. (Message: Expected J.183/JCTEA format on Frequency 'id' : 'type')</p> <p>3) The QAM card is unable to synchronize with the J.183/JCTEA formatted stream. Possible packet loss in the input stream. (Message: Unable to sync to J.183 stream on Frequency)</p>
No Lock	4390932	critical	No valid transport stream detected on input port.
BER/PER high	4390933	critical	Bit/Package error rate is too high.
BER/PER high	4390934	warning	Bit/Package error rate too high.
PLP not found	4390937	critical	Configured PLP missing from input. First PLP available chosen.
Emergency broadcast detected	4390940	critical	The demodulator has detected the announcement_switching_flag_field is set to 1 in the incoming TS header, indicating an emergency broadcast is active.
LNB power supply error	4390956	critical	<p>This alarm may be raised due to several reasons:</p> <ul style="list-style-type: none"> <li>- Too high temperature on the demod chip.</li> <li>- Problems with the power delivery on the card, i.e hardware failure</li> <li>- Problems with the external LNB.</li> </ul>
Inaccurate configuration	4390971	notify	Constellation or code rate on frequency on input does not match configuration.
The spectrum inversion is different than the configured one	4390980	notify	Hot swapping with an older revision input card won't work.
The constellation is different than the configured one	4390981	notify	Hot swapping with an older revision input card won't work.
MER less than lower limit	4390994	warning	Low signal quality.

## 7 ECMG

Error Code	ID	Level	Description
ECM repetition rate might be too large	1048628	warning	In PVR assist mode it is required to play out an ECM for each access points in the stream. This alarms indicates this is not possible as the access points occur more frequent than the allowed ECM playout rate. Try to reduce the ECM playout rate dictated by the CA system.
No ECMG connection	4259941	critical	No TCP/IP connection established with the ECMG.
Channel not open	4259942	critical	The DVB ECM channel is not set up.
Error reported by the ECMG	4259943	critical	<p>The ECMG is in error state and reports to the scrambler card. An error ID and description may be associated:</p> <p>ID Description:</p> <ul style="list-style-type: none"> <li>0x0000 DVB reserved</li> <li>0x0001 Invalid message</li> <li>0x0002 Unsupported protocol version</li> <li>0x0003 Unknown message_type value</li> <li>0x0004 Message too long</li> <li>0x0005 Unknown Super_CAS_id value</li> <li>0x0006 Unknown ECM_channel_id value</li> <li>0x0007 Unknown ECM_stream_id value</li> <li>0x0008 Too many channels on this ECMG</li> <li>0x0009 Too many ECM streams on this channel</li> <li>0x000A Too many ECM streams on this ECMG</li> <li>0x000B Not enough control words to compute ECM</li> <li>0x000C ECMG out of storage capacity</li> <li>0x000D ECMG out of computational resources</li> <li>0x000E Unknown parameter_type value</li> <li>0x000F Inconsistent length for DVB parameter</li> <li>0x0010 Missing mandatory DVB parameter</li> <li>0x0011 Invalid value for DVB parameter</li> <li>0x0012 Unknown ECM_id value</li> <li>0x0013 ECM_channel_id value already in use</li> <li>0x0014 ECM_stream_id value already in use</li> <li>0x0015 ECM_id value already in use</li> <li>0x7000 Unknown error</li> <li>0x7001 Unrecoverable error</li> <li>0x???? User defined error</li> </ul>
Wrong version or data sync lost	4259946	critical	Either the DVB-SIM version sent by the ECMG is wrong or the scrambler card cannot synchronize the data stream with the ECMG.
No ECM received for the Crypto-Period	4259948	major	The ECMG doesn't reply ECMs in 2 Crypto Period time after receiving the Control Word provision from the scrambler card.
ECMG maximum ECM streams reached	4259951	warning	The scrambler card is opening more ECM streams than the maximum declared by the *ECMG.
EIS recommended CP is lower than the ECMG minimal CP	4259952	warning	The EIS scheduler is setting the Crypto Period (CP) time shorter than the minimal CP declared by the ECMG.

Error Code	ID	Level	Description
Error reported by the Peer	4259953	major	<p>The Peer scrambler card is in error state and reports to the scrambler card. An error ID and description may be associated:</p> <p>ID Description:            0x0001 Unknown SCG_id            0x0002 Unknown ECM_Prefered_Pid            0x0003 CW too short            0x0004 CW too long            0x0005 ECM too short            0x0006 ECM too long            0x0007 Invalid ECM format            0x0008 Invalid time            0x0009 Missing CWs</p>
No peer scrambler card connection	4259954	critical	No connection is established with the Peer scrambler card.
Unknown scgld reference	4259955	major	The Peer scrambler card sends a message in which the reference scgld doesn't exist.
Unknown connection	4259956	major	The Peer scrambler card trying to connect is not matching the one configured in its IP filtering value.
The ECMG defines a NULL delay_start value (not recommended).	4259957	warning	A delay_start value = 0 ms, implies that the change of the transmitted ECM values happens simultaneously with the change of the Control Words used for scrambling the media. This may cause a synchronization problem for the STB.
Unknown scg ID	4456549	critical	CA-Proxy client is configured with different SCG than is the case on this server.
Unknown ca-proxy client serial	4456550	critical	Client not in proxy client list or serial number is wrong.
CA-Proxy client is disconnected	4456551	major	No contact with client.

## 8 EIS

Error Code	ID	Level	Description
No EIS connected	3145829	warning	The EIS is not connecting to the scrambler card
Error reported by the EIS	3145830	warning	<p>The EIS is in error state and reports to the scrambler card. An error ID and description may be associated:</p> <p>ID Description:</p> <p>0x0000 DVB reserved</p> <p>0x0001 Invalid message</p> <p>0x0002 Unsupported protocol version</p> <p>0x0003 Unknown message_type value</p> <p>0x0004 Message too long</p> <p>0x0005 Inconsistent length for parameter</p> <p>0x0006 Missing mandatory parameter</p> <p>0x0007 Invalid value for parameter</p> <p>0x0008 Unknown EIS_channel_ID value</p> <p>0x0009 Unknown SCG_ID value</p> <p>0x000A Maximum SCGs already defined</p> <p>0x000B Service level SCG definitions not supported</p> <p>0x000C Elementary Stream level SCG definitions not supported</p> <p>0x000D Activation_time possibly too soon for SCS to be accurate</p> <p>0x000E SCG definition cannot span transport boundaries</p> <p>0x000F A resource does not exist on this SCS</p> <p>0x0010 A resource is already defined in an existing SCG</p> <p>0x0011 SCG may not contain one or more content entries and no ECM_Group entries</p> <p>0x0012 SCG may not contain one or more ECM_Group entries and no content entries</p> <p>0x0013 EIS Channel_ID value already in use</p> <p>0x0014 Unknown Super_CAS_Id</p> <p>0x7000 Unknown Error</p> <p>0x7001 Unrecoverable Error</p>
Unknown channel ID value	3145831	warning	The EIS is sending a message in which the reference channel isn't defined.
Soap connection error	3145832	warning	The scrambler card cannot connect to the MMI card in order to send EIS commands with SOAP.
Unknown remote	3145833	warning	The EIS trying to connect to the scrambler card is not matching the one configured the IP filtering value. See EIS node on the GUI.
Provision: Unknown (CasId, SubId)	3145834	warning	Spelling error in message.
Provision: Unknown networkId or/and transportId	3145836	warning	The EIS send a scrambling provision which refers to a network ID and/or a transport ID at the output which doesn't exist.
Provision: Unknown output serviceId(s)	3145837	warning	The EIS send a scrambling provision which refers to an output service which doesn't exist.
Provision: Unknown output PID	3145838	warning	The SCG provision scheduled by the EIS service refers to an output PID which doesn't exist for the given Net ID and TS ID.

Error Code	ID	Level	Description
Provision: Unknown error	3145839	warning	The EIS scrambling provisions which can't be executed because of an error non-identified.
Provision: No ECM group defined	3145840	warning	The EIS sends scrambling provisions for output service, but forgets to associate the ECMs.
Provision: No services or components defined	3145841	warning	The EIS sends scrambling provisions with ECMs, but forgets to associate the services/components.
Unknown scgld value	3145842	warning	The EIS sends messages in which the scgld reference is not set-up.
Provision: Invalid scgld value	3145843	warning	The provision sent by the EIS cannot be carried out because the ECM used for the scrambling belong to an SCG_ID which isn't not defined in the MUX.



## 9 EMMG/PDG

Error Code	ID	Level	Description
Total EMM bandwidth exceeded	3539046	warning	The total bandwidth used by all the emm/pd streams exceeds the maximum of 3Mbit/s
Unknown connection	3539047	critical	The EMMG trying to connect to the scrambler card is not matching the one configured the IP filtering value. See EMMG/PDG node on the GUI.
No EMMGs/PDGs connected	3539048	critical	The EMMG/PDG is not connecting to the scrambler card
Wrong data type stream requested by the EMMG/PDG	3539049	critical	The EMMG/PDG is trying to open a type of stream (EMM or PD) which is not matching the type (EMM or PD) sets on the scrambler card.
Error reported by the EMMG/PDG	3539050	critical	<p>The EMMG is in error state and reports to the scrambler card. An error ID and description may be associated.</p> <p>ID Description:</p> <ul style="list-style-type: none"> <li>0x0000 DVB reserved</li> <li>0x0001 Invalid message</li> <li>0x0002 Unsupported protocol version</li> <li>0x0003 Unknown message_type value</li> <li>0x0004 Message too long</li> <li>0x0005 Unknown data_stream_id value</li> <li>0x0006 Unknown data_channel_id value</li> <li>0x0007 Too many channels on this MUX</li> <li>0x0008 Too many data streams on this channel</li> <li>0x0009 Too many data streams on this MUX</li> <li>0x000A Unknown parameter_type</li> <li>0x000B Inconsistent length for DVB parameter</li> <li>0x000C Missing mandatory DVB parameter</li> <li>0x000D Invalid value for DVB parameter</li> <li>0x000E Unknown client_id value</li> <li>0x000F Exceeded bandwidth</li> <li>0x0010 Unknown data_id value</li> <li>0x0011 Data_channel_id value already in use</li> <li>0x0012 Data_stream_id value already in use</li> <li>0x0013 Data_id value already in use</li> <li>0x0014 Client_id value already in use</li> <li>0x7000 Unknown Error</li> <li>0x7001 Unrecoverable Error</li> </ul>
Invalid client ID received	3539051	critical	The EMMG is sending wrong client ID reference in its messages.
No data sent by EMMG/PDG	3539052	warning	The EMMG/PDG didn't send any EMM/PD data 20 seconds after the establishment of the connection
EMMG/PDG message is missing mandatory parameter	3539053	critical	The EMMG/PDG is sending incomplete messages with missing mandatory parameters.
EMMG/PDG requests Client_id value already in use	3539054	critical	The EMMG/PDG is trying to open a EMM channel (channel_setup) by using a client ID already in used.
EMMG/PDG requests an unknown data_stream_id value	3539055	critical	The EMMG/PDG is sending EMM/PD data in a stream which is not opened.

Error Code	ID	Level	Description
Input EMM/PD buffer overflow. Packets lost.	3539056	critical	The buffer of the enabled EMM/PD flow control function, in the MUX is overflowed. It happens, when the EMMG/PDG server is sending EMM/PD data with a bitrate higher than the one set in the GUI.

## 10 EPG

Error Code	ID	Level	Description
Unable to keep the assigned playout rate	3342636	warning	The EPG card is not able to play out at the rate defined by the user. Try to reduce the rate specified at the MPTS output configuration node.
Manually set source not found	3342637	warning	User has selected a source that no longer exist on input
Unable to communicate with the playout app	3342638	critical	There are two applications running on the EPG card, analyzer and playout. Currently the analyzer is unable to communicate with the playout.
Incoming EIT not complete	3342639	warning	The incoming EIT information is missing at least one section it is signaled to have.
Source has no incoming events	3342640	warning	There is no EIT events in the source data. Change the data source.
Last event starts after 64 days, dropping event	3342641	warning	The EIT guidelines does not allow EIT data further in the future than 64 days. Either the incoming data goes further than that into the future, or the local time is not correct on the card
Too many events within 3 hour period to follow recommendations, dropping event	3342642	warning	To follow the recommendations we only have 8 EIT sections of 4096 bytes available for each 3 hour period. If more information than can be fitted inside this data size is received, some will be dropped.
Bad EIT input. Inconsistent version numbers or CRC values, entering accumulation mode	3342643	warning	Input data faulty. EIT data might be inconsistent.
PF demands higher bandwidth than configured EIT rate	3342644	warning	Reserved bandwidth for EPG is too low.
Unable to communicate with peer	3342645	critical	EPG Sync unable to connect to peer.
Peer stream DID-NID-TSID conflicts with local stream	3342646	warning	TS clash between two peers. Same domain id, network id, and TS id on both peers.
Unable to communicate with the analyzer app	3342647	critical	There are two applications running on the EPG card, analyzer and playout. Currently the playout is unable to communicate with the analyser.

## 11 Encoding

Error Code	ID	Level	Description
Delay buffer overflow	1048588	critical	This may be because the total bitrate of the MPTS components exceeds the maximum rate configured for the port.
No SDI sync	3997696	critical	Wrong format or no input.
Wrong SDI input format	3997697	critical	Wrong SDI input format.
No video input.	3997698	critical	No video input detected.
No video frames decoded	3997699	critical	Video is not being decoded.
No video frames encoded	3997700	critical	Video is not being encoded.
No transport stream output	3997701	critical	Encoder is not producing any output data.
No audio received	3997702	critical	No audio received.
No audio encoded	3997703	critical	Audio is not being encoded.
Audio in/out format mismatch	3997704	critical	Configured audio output format not compliant with audio input format.
Video bitrate too high	3997705	major	Video bitrate too close to multiplex bitrate.
No PIP frames encoded	3997706	critical	PIP video is not being encoded.
In/out format mismatch	3997707	warning	Configured video output format not compliant with video input format.
Asynchronous audio	3997708	warning	Passthrough audio: Embedded audio is asynchronous to the video.
Audio PID scrambled	3997711	critical	The incoming audio PID is scrambled. Make sure the source is in clear.
No audio to transcode	3997712	critical	Audio is not being transcoded.
No audio decoded	3997713	critical	Missing input data or decode failure.
In/out frame rate mismatch.	3997714	critical	The input frame rate is not compliant with the configured output frame rate.
Missing DPI from input	3997716	warning	Unable to obtain DPI from the input.
Missing WSS from input	3997717	warning	Required WSS information not found on the input.
Missing VPS from input	3997718	warning	Required VPS information not found on the input.
Missing Teletext from input	3997719	warning	Required Teletext information not found on the input.
In/out aspect ratio mismatch	3997720	warning	The configured output aspect ratio is not compliant with the input aspect ratio.
Channel timeout	3997721	warning	Internal error, channel will be restarted.
RF input frequency not locked	3997722	critical	No signal found on configured RF frequency.
Mismatch analog video format, no video encoded	3997723	critical	Detected analog video format does not match configured video format.
No lock on video input	3997724	critical	Missing video or invalid input video format.
Audio clipping. Input level is too high	3997725	major	Audio clipping. Input level is too high.
Audio silent.	3997726	notify	Audio level has been silent for a prolonged period of time.
Unknown input video format	3997727	warning	Unknown input video format.

Error Code	ID	Level	Description
Unknown input aspect ratio	3997728	warning	Unknown input aspect ratio.
Illegal configuration. Two services and one FHD	3997729	critical	At least one of the channel pairs A/B and C/D is configured using two input services of which at least one is Full HD. This is not supported by the Transcoder MS card.
Unsupported number of audio channels on input	3997730	critical	Exceeded the number of supported audio channels on the input.
SD to HD upscaling is not supported	3997731	major	SD to HD upscaling is not supported.
Logo insertion failed	3997732	major	Logo image could not be downloaded from MMI or could not be read.
No lock on SDI input.	5177345	critical	Wrong format or no input.
No TS input	5177346	critical	No TS input is detected.
Service scrambled	5177347	critical	The incoming PID is scrambled. Make sure the source is in clear.
No audio stream matched the configuration	5177348	critical	No audio stream matched the configuration.
No audio on sdi input	5177349	critical	No audio is detected on the SDI input.
No audio input detected	5177350	critical	No audio is received.
No audio decoded	5177351	critical	No audio is being decoded.
Audio input is multichannel.	5177352	warning	Audio input is multichannel
No audio output	5177353	critical	No audio is being encoded or passed through.
Expected format mismatch	5177354	critical	Expected format is not matching the input format.
No video input detected	5177355	critical	No video detected on the input.
SD on HD channel	5177356	critical	SD is not supported in this mode
HD on SD channel	5177357	critical	HD video is not supported in this mode.
No video decoded	5177358	critical	Video is not being decoded.
Frame rate domain mismatch	5177359	critical	Frame rate domain mismatch between configuration and decoded streams.
Unsupported input to output frame rate conversion.	5177360	critical	The incoming frame rate is not compliant with the configured output framerate.
License violation - Video Decode Profile 10bit 4:2:2	5177361	critical	The 4:2:2 Video license is not installed on the coder card.
No video encoded	5177362	critical	Video is not being encoded.
Video QP is higher than expected	5177363	notify	The QP of the encoded video is higher than expected.
Local PCR out of sync. Resynchronizing	5177364	notify	Local PCR out of sync. Resynchronizing
Forced signal loss	5177365	notify	Forced signal loss.
Black frame detected	5177366	warning	Input signal is black frames.
Freeze frame detected	5177367	warning	Input signal is frozen frames.
External audio metadata settings invalid	5177368	warning	The incoming SDI signal does not contain audio metadata which can be merged with the current metadata configuration.

Error Code	ID	Level	Description
External metadata does not contain selected program number	5177369	warning	The audio metadata in the incoming SDI signal does not contain the selected program number. This may cause the output signalling to be incorrect for the audio component.
Input audio does not contain selected program number	5177370	critical	The incoming audio does not contain the selected program number.
Invalid audio samplerate	5177371	critical	The samplerate of input audio is not valid (48Khz only is supported).
Presentation problem for DVB subtitle	5177372	warning	Problems converting EBU Teletext subtitle to DVB Subtitle. Text can be lost.
Output channel mode changed to match input.	5177373	warning	The output channel mode configuration contained channels that were not present in the input and has been reverted to match the input channel mode.
Output bitrate reduced to match input.	5177374	warning	The output bitrate configuration exceeded the bitrate of the input and has been reduced to match the input bitrate.
Audio input format mismatch.	5177375	critical	The audio received does not match the expected format (PCM/compressed data).
No lock on sdi input for MSE	5177376	critical	System alarm used for redundancy triggerering on multi-screen encoder
Scaling mode requires both channels to have same input format	5177378	critical	Dual HD scaling requires channel A and B (C and D) to have the same input format.
No video output	5177379	critical	No video is output.
Active SDI input due to redundancy switch.	5177380	notify	A switch has taken place due to no SDI lock, based on current redundancy mode.
AES67 regulator restarted	5177381	critical	Regulator has restarted the last second due to overflow or too large RTP interval.
Invalid audio channel mode	5177383	warning	The channel mode of input audio is not valid (Dual mono not supported, fall back to left channel).
True peak exceeds the maximum permitted level -1 dBTP.	5177384	warning	According to EBU R 128, the limit for the production level is specified at -1 dBTP.



## 12 Encryption

Error Code	ID	Level	Description
Input scrambled (SCR)	1048602	critical	Service scrambled on SCR input.
Input scrambled (IP)	1048603	warning	Service scrambled on IP input.
Scrambling manually disabled	1048607	notify	Scrambling is configured, but disabled.
Descrambling failure	1048613	critical	Descrambler unable to descramble selected service. Please check that the system has access to the service.
Algorithm mismatch	1048626	critical	Algorithm mismatch between the card setup and the selected in the configuration.
Access point not detected	1048627	critical	In some PVR modes, typically Irdeto AP alignment and PVR assist modes, the ECM are no longer played out based on the repetition rate only but based on what is called an Access Point. The Access Point definition is not specified but it is typically a specific point inside the stream at which we want to insert an ECM packet. In Irdeto AP alignment mode, the Access Point criteria is chosen by the user while in PVR assist, the Access Points are automatically selected by the FPGA.
SSM not installed	3473415	critical	The selected SSM is not present in the card. This situation may occur if a bulk descrambler card is hot swapped, and the new card does not contain the SSM currently selected for this slot.
Bulkdescrambler not authorised. All services blocked	3473416	critical	The Latens system manager has not yet authorized the unit.
Latens controller connectivity failure	3473417	major	The unit is not able to communicate to any of the defined Latens Controllers
SSM loading failure	3473418	critical	The system failed to load the selected SSM. The SSM is present on the card, but loading failed.
Unexpected SSM	3473419	critical	The linked SSM is not matching the selected one.
Key failure	3473420	critical	The ECM does not decrypt. It could be either a faulty ECM or that the descrambler do not have access. The specific reason will be part of the alarm text.
CA System: Unable to retrieve the Control Word	3473421	critical	No response from CA system.
SIM card: No EMM	3473423	warning	See EMM source on the conditional access pages, and verify presence of EMM with correct CAS ID.
The ECM associated is not authorized	3473424	critical	A missing EMM source could cause this problem. Alternatively check the subscription rights with the source vendor.
SIM card: Not supported	3473425	critical	This smartcard is not recognized by the HW.
SIM card: Not powered	3473426	critical	Internal card failure.
SIM card: Missing	3473427	critical	Check that the smartcard is properly fitted.
SIM card, no ECM	3473428	critical	Verify presence of ECM with correct CAS ID, and service is assigned to the correct descrambler.
Descrambling failure (Rating Level)	3473429	critical	ECM rating level is higher than the allowed rating level set in the descrambler
SIM card: High load	3473430	warning	The smart card is processing data at max capacity. Distribute CA resources to avoid any issues.

Error Code	ID	Level	Description
Detected change in ECM rating level	3473431	notify	ECM rating level has changed
Configured operator id not found in ECM	3473433	critical	A specific operator id is set in the descrambler, but no ECM with this operator id is received
VPN Certificate files missing	4587576	critical	VPN certificates are used by the CA Proxy solution. Please install a valid certificate to proceed.

## 13 License

Error Code	ID	Level	Description
Running demo license	65636	notify	Notification that a demo license is being used.
License violation: 4 channel license installed only	1048647	critical	License violation. 4 channel license installed, 8 channels configured. Channels C1,C2,D1,D2 is muted.
Running demo license (UMOD)	1048676	notify	Notification that a demo license is being used. This alarm is generated for all the UMOD based cards.
License Violation	3080282	critical	A feature without license is being used.
HD video license violation	3997715	warning	The HD Video license is not installed on the coder card, hence the configuration is rejected.
No DVB-S2X license.	4391002	critical	A DVB-S2X license is required for S2X specific modulation and code rates. Port is muted.

## 14 Maintenance

Error Code	ID	Level	Description
Invalid URL for automatic configuration backup	5111917	major	Check the connection to the ftp server, and verify correct user and password is used.

## 15 Modulation

Error Code	ID	Level	Description
PLL lock error	1048604	critical	Hardware error.
Bad channel spacing	1048648	critical	When using 8 channels, distance between each channel of a pair must be 7 or 8 Mhz.
Calibration data missing	1048649	critical	Calibration data not set or corrupted.
No clock reference sync	1048652	critical	Outputs will be muted for all cards which requires accurate clock when the clock is not available
T2MI CC counter error	1048653	critical	CC errors detected on the incoming T2MI TS packets
DVBT2 reset chain error	1048654	critical	
DVBT SFN Mip Status Missing	1048655	critical	Mip packet in incoming stream not found.
DVBT SFN Bandwidth Mismatch	1048656	critical	The bandwidth setting must be identical on both MIP inserter and modulator side.
DVBT SFN Sync Error	1048657	warning	Internal clock not locked to reference.
DVBT SFN Output missing	1048658	critical	No signal detected after output amplification stage. Possible hardware failure.
No bitrate/No lock on DAB mux	1048664	critical	No DAB mux found on input
FEC on EDI input not supported	1048665	critical	The EDI source contains FEC. This is not supported.
Packets lost on DAB mux	1048666	critical	The incoming DAB mux is not complete.
DAB mux has been reconfigured	1048667	notify	The incoming DAB mux structure has changed. This affects the output while output reconfiguration.
DAB mux out of sync	1048668	critical	The internal clock system is not able to sync with the incoming DAB mux
Carrier wave mode enabled	1048671	critical	Sending test signal.

## 16 Monitoring

Error Code	ID	Level	Description
PID bitrate below threshold	1048685	major	The PID bitrate is below the limit configured in Monitoring.
CC errors above threshold	1048686	major	The amount of CC errors is above the limit configured in Monitoring.
PID not present	1048687	major	A signalled component in a monitored service is not present on the input.
No PCR present on PCR PID signalled in PMT	1048688	major	The PCR PID signalled in PMT does not contain PCR.



## 17 Network

Error Code	ID	Level	Description
Half duplex link	1048581	major	<p>Only half duplex link has been negotiated with network equipment. Please change configuration on network equipment to full duplex and reboot input card.</p> <p>Note: There is a known problem in the eth hw that will cause the link to enter Half Duplex mode when the negotiated speed is different from 1000. In these cases it may help to manually configure the port to the same speed as the other side.</p> <p>The negotiated speed and the speed selection is found under the admin pages.</p>
Receive frame error	1048586	warning	A low level protocol error was detected in the incoming Ethernet packet.
Frame length error	1048595	critical	An incoming IP packet had an illegal length field.
IP fragmentation detected - format not supported	1048596	critical	Fragmented packets are not supported.
Reduced dataport link speed	1048605	major	The input dataport is set to automatic speed, but the the negotiated network speed is less than 1000.
Link down input	1048611	critical	No link with network equipment.
Link down output	1048612	critical	No link detected on the indicated Ethernet port.
Link down on input interface	1048619	major	No link with network equipment on one of the IP interfaces.
Unsupported extension headers	1048622	critical	Packets dropped because they contain IPv6 extension headers.
Link down on output interface	1048670	major	No link with network equipment on one of the IP interfaces.
VCAS not connected	3473507	critical	No connection to the conditional access system server.
Control port link down	3539045	critical	The card is not physically connected to the network.
Control port link down	4259950	critical	The card is not physically connected to the network.
No PIM neighbour router connection	4915501	major	Unable to form OSPF relationship with neighboring router.
No OSPF neighbour router connection	4915502	major	Unable to form OSPF relationship with neighboring router.
OSPF MD5 authentication expected	4915503	major	Router does not send MD5 authentication.
OSPF MD5 authentication required	4915504	major	Router requires MD5 authentication.
OSPF MD5 authentication failed	4915505	major	MD5 authentication failed.
IP output LINK-DOWN is notified through OSPF	4915507	warning	OSPF server has notified the router that current service is down.

## 18 PSI

Error Code	ID	Level	Description
PAT Missing	2883584	critical	PAT is missing for the indicated input ID. Raised for inputs in which is used as part of the live configuration only.
PMT Missing	2883585	critical	PMT is missing for the indicated input and service id. Raised for services in which is used as part of the live configuration only.
PAT analyze temporarily disabled	2883586	critical	The PSI analysis algorithm has detected too frequent PAT changes which generally indicates problem with the incoming PSI.
PMT maps pid to reserved range	2883587	critical	The PSI analysis has found pids mapped in PMT that is reserved in the selected PSI analysis algorithm
Missing ECM update to playout	4260590	critical	No ECMs are sent to the ECM player.
Received late ECM to playout	4260591	warning	An ECM is in late and cannot be played out by the ECM player.
Lost ECM to playout	4260592	warning	An ECM is missing to the ECM player.

## 19 PSIREGEN

Error Code	ID	Level	Description
TS not present for content switching	4325386	critical	Transport stream that is configured for content switching is not present.
Target service not present for content switching	4325387	major	Target service that is configured for content switching is not present.
Content service not present for content switching	4325388	major	Content service that is configured for content switching is not present.

## 20 Radio

Error Code	ID	Level	Description
No data input	1442192	critical	The Radio card does not receive any of the expected data.
No MPEG audio frames in stream	1442193	critical	Cannot output audio because there is no MPEG audio in the stream.
Low/high buffer filling	1442194	warning	Buffer usage is high.
Unsupported MPEG audio	1442195	critical	Cannot output audio because the MPEG audio in the stream is not supported.
Temperature high - Please check cooling	1442198	warning	The card temerature is exceeding the recomendations
Low output power	1442200	critical	Output level is significantly lower than expected.
Test tone enabled	1442201	warning	Test tone playing instead of MPEG audio.
Switched	1442202	notify	The internal redundancy module has switched to the other backplane.

## 21 Redundancy

Error Code	ID	Level	Description
No connection to twin GW	1048631	critical	The main communication link between the redundant gateways is not responding. Note, the gateway redundancy is currently unavailable.
No redundant connection to twin GW	1048632	warning	The backup communication link between the redundant gateways is not responding. Note that the link between the gateways are still operational via the main communication link.
T2MI stream configuration mismatch	1048633	warning	T2MI gateway redundancy requires identical T2MI output stream configurations on both gateways. /
No matching stream found on twin GW	1048634	warning	T2MI gateway redundancy requires two streams with the same pairing id.
T2MI relay switched, using local source	1048635	notify	The T2MI gateway is currently using the backup gateway source.
T2MI relay in fallback, using unsynchronized local source	1048636	warning	The other gateway is not responding, hence a switch to this gateway has happened.
Source A disabled	1048638	warning	The IP seamless input ports may be manually disabled. This will force the seamless input logic to use the other input, i.e input B
Source B disabled	1048639	warning	The IP seamless input ports may be manually disabled. This will force the seamless input logic to use the other input, i.e input A
Active Input Redundancy Switch	2621440	critical	A switch has been performed due to a reason. The backup equipment is in use.
Twin MMI configured for Internal Redundancy. Config sync will not work	2621534	warning	In MMI redundancy mode both MMI cards must be defined to be in MMI redundancy mode. Use Maintenance centre to change this mode.
Unable to communicate with TWIN MMI	2621536	critical	Check that the two MMI control ports are able to communicate via the external control port.
MMI Redundancy disabled in Twin MMI. Config sync will not work	2621537	warning	MMI redundancy must be enabled in both MMI boards in order to get database synchronization and cards. If only one MMI enables this redundancy, it will not work. Make sure both sides are enabled.
Config sync not available due to MMI cardtype mismatch	2621538	critical	In a TWIN MMI configuration the two MMI cards need to be identical.
Config sync not available due to MMI software version mismatch	2621541	critical	Same software version is required to allow database synchronization in MMI Redundancy environment.
This MMI is not active. Go to Twin MMI to configure cards	2621542	warning	For those units with MMI Redundancy, one of the MMI boards will be spare or not active, so it will not have any control on slave cards. This alarm acts as reminder for the user to avoid configuring cards in the wrong MMI.
Twin MMI IP address cannot be the same as its own MMI IP address	2621543	critical	Please check the IP settings for the twin MMI:
Communication lost to external SDI switch	2621547	warning	Communication to external SDI switch has been lost, so any N+M Redundancy switch for encoders using the mentioned SDI switch will not work.

Error Code	ID	Level	Description
Redundancy configuration consistency broken. Switch might fail	2621548	warning	An internal alarm, please contact support
Card redundancy switch failed	2621549	warning	Due to a communication error to the external SDI switch, the N+M switch to spare has failed.
Card redundancy: Redundancy switch completed	2621550	critical	It's a placeholder for alarms like:  Card redundancy: Switched from slot X to backup in slot Y  This indicates that the particular redundancy switch completed successfully
Switched, reason: Logout	2949192	notify	The internal redundancy module switched to the other input card because it lost contact with the login server on the MMI board.
Switched, reason: No bitrate	2949193	notify	The internal redundancy module switched to the other input card due to no bitrate on the backplane.
Switched, reason: Operator	2949194	notify	The internal redundancy module switched to the other input card due to a command from the user.
Cannot switch, reason: no MMI detected on the other backplane	2949240	notify	Most cards has status about the presence of the other MMI card. If this state indicates no MMI on the other backplane then the switch is not executed..
CA Redundancy using backup ECMG	3211365	major	CA Redundancy switched to backup.
Output faulty	4915506	major	The output redundancy module will raise this alarm when output ports are muted. This alarm is a good candidate to use as a switching trigger for external switches.



## 22 Statmux

Error Code	ID	Level	Description
Failed to add channel	5242880	major	Failed when attempting to add a new channel. This may be caused by card missing.
Channel has different codec from group	5242881	major	Channel has a different codec from the rest of the group.
Group rate is configured too low	5242882	major	The group rate is too low because it is not enough bitrate left for the video PIDs. Increase group rate, reduce the number of channels or reduce the number of non-video PIDs per channel.
Lost contact with controller	5242883	critical	Lost contact with the controller.
Channel experiences disturbances	5242884	critical	Controller is incapable of controlling channel properly.
General Statmux controller error	5242885	critical	General Statmux controller error.
Controller paused	5242886	critical	Controller paused due to clock synchronization

## 23 Stream

Error Code	ID	Level	Description
No sync	1048576	critical	No ASI input sync detected.
No bitrate	1048580	critical	No bitrate detected on multicast/unicast address on the indicated input interface.
IP dejitter buffer >75%	1048582	warning	Jitter on incoming data is high. Possible problem with the PCR on the input stream.
IP dejitter buffer >95%	1048583	critical	Jitter on incoming data is close to exceeding buffer. Possible problem with the PCR on the input stream.
Input buffer overflow. Packet dropped	1048584	critical	Transport stream input buffer is overflowing. Packets are dropped. In the rare cases when this happens it is usually due to a configuration where one service has been used for multiple outputs. The input card is able to copy services in this manner but at some point the copy process will be too time consuming which causes input packets to be lost.
ATV CC error	1048585	critical	This means that packets are lost internally.
Back-plane bitrate exceeded. Packets dropped.	1048587	critical	TS packets dropped.
No signal	1048589	critical	This indicates that no data is received to the input module at all. It is triggered only if one or more inputs are configured.
Multiple input sources, input temporarily disabled	1048594	critical	The same multicast stream arrives to the unit from different sources. The input will automatically be disabled until one source is detected only.
TS packet sync byte error	1048597	critical	Sync byte error not detected or located at an unexpected location.
Invalid PCR	1048598	warning	Unexpected PCR interval detected. Multiple of these may result in regulation overflow.
Regulation overflow	1048599	warning	The de-jitter algorithm was unable to recover the input signal. To recover the input buffers are flushed.
System clock frequency outside specification	1048600	warning	The PCR of the outgoing stream ends up with a PCR outside the specification. This could be caused by too much input jitter, or that the internal algorithm fails due to missing packets on the input.
PID Missing	1048601	major	An expected PID is missing.
PCR missing in PCR PID	1048606	critical	PCR expected in PID.
Recommended input maximum bitrate exceeded	1048608	warning	Input bitrate too high.
Recommended output maximum bitrate exceeded	1048609	warning	Output bitrate too high.
CBR de-jitter measurement	1048614	warning	Measuring stream before de-jittering. Measurement time depends on bitrate and jitter.
No bitrate on interface A	1048617	warning	No bitrate detected on multicast/unicast address on the indicated input and interface.
No signal on interface	1048618	major	This indicates that no data is received to the input interface at all. It is triggered only if one or more inputs are configured.

Error Code	ID	Level	Description
Relative delay >100 ms	1048620	warning	Buffer almost full. Danger of not being able to switch seamlessly.
Inputs not synchronized	1048621	warning	Seamless switching may not work properly because the inputs are not synchronized. This may be because RTP is not used on the input streams.
Low/medium priority packets dropped	1048624	major	Packets from low or medium prioritized transport streams are being dropped from the output buffer because the total output rate exceeds the capacity of the output card.
CC Error On Input	1048629	warning	CC-Error has been identified on the input.
No bitrate on interface B	1048637	warning	No bitrate detected on multicast/unicast address on the indicated input and interface.
Input overflow on data sources	1048641	warning	In data sources, some of the frames have been dropped due to input overflow.
Output bitrate exceeded	1048669	critical	This may be because the total bitrate of the MPTS components exceeds the maximum rate configured for the port.
Monitored input missing	1048672	warning	No bitrate detected on the interface A on the indicated input. Unmuting corresponding output.
Unexpected start of payload	1048677	major	Unexpected start of payload.
Unexpected adaption field length	1048678	major	Unexpected adaption field length.
Sync distance not byte aligned	1048679	major	Sync distance not byte aligned.
Data field length not byte aligned	1048680	major	Data field length not byte aligned.
Sync byte error	1048681	major	Sync byte error.
Packet cnt error	1048682	major	Packet cnt error.
TS error indicator set	1048683	major	TS error indicator set.
BB header crc8 error	1048684	major	BB header crc8 error.
IP source muted	4915500	warning	Source turned off because of other error.
Source IP also defined outside redundancy group	4915508	warning	When a source IP present inside a redundancy group is also defined outside of the group, the network might not switch
File streaming bitrate exceeds limit	5505025	warning	The total bitrate of all streamed TS files exceeds the recommended limit of 10 Mbps.
Error accessing or parsing TS file	5505026	warning	Error accessing or parsing TS file. Reasons for this can be e.g. that the file is not a raw TS file, file not present, network problems in case of a file located on a NAS.
Error streaming TS to FPGA	5505028	warning	Communication issue between CPU and FPGA (socket related).

## 24 System

Error Code	ID	Level	Description
System Reference Clock Failure	1048590	critical	The system clock signal from the switch card is not detected by the FPGA. The switch card may be broken.
System Reference Clock Unsynchronised	1048591	critical	The card has detected a situation where the internal clock needed to re-sync to the reference clock.
Card Overheated	1048592	critical	The card temperature is too high. Check the unit and make sure the ventilation vents are positioned correctly.
Input genlock reference signal not present	1048623	warning	Genlock is enabled but nothing is feeding the sync in port.
No contact with FPGA.	1048625	critical	The local FPGA is not responding. This could be due to a mismatch of the software version and the FPGA image. Try to re-install the software on the card.
Hardware failure	1048640	critical	Could be generated due to -Ethernet link is down on both dataports on a SWIP card
Low output power	1048651	critical	No output signal measured. Possible hardware failure.
UMOD card booted with fallback FPGA	1048659	critical	Error loading firmware. Card must be reprogrammed.
Modulator card not supported	1048660	critical	The modulator FPGA id is unknown. This could be hardware failure or a corrupt image. try to reload modulator software.
Clock-ref card in the wrong slot	1058577	critical	Clock-ref card must be placed in slot 1.
GPS antenna not connected	1058578	critical	GPS antenna must be connected.
No GPS module on 1RU	1058579	critical	The unit has been configured to include a GPS module, but this module is not reachable.
Card missing	2621490	critical	A previously registered module is not present in the chassis.
Card mismatch	2621491	critical	The card inserted to the slot does not match the card type that is expected. If the new card is intended for the slot, remove the card, then go to the about page and accept changes (this removes the previous card history for the slot), then insert the new card again.
Alarm History Cleared	2621493	notify	Indicates in the alarm history log when the alarm history was clear by the user.
Card rejected due to conflict	2621494	warning	A card is rejected from login because the chassis contains another cards functionality is conflicting
Card does not support MMI Redundancy	2621497	critical	MMI redundancy is supported by a selection of cards only. The current card is either running too old software or it does not support this feature.
Unsupported version	2621535	major	Software version not supported.
SIM card reader connection error	3473414	critical	There is a communication problem with the Smart Card Reader. A reboot might be required after upgrade.
Smart Card Reader firmware version mismatch	3473422	warning	Mismatch between the installed Smart Card Reader firmware and the one required by the software application.
SSH login password on MMI is reset to default	3932161	notify	SSH login password on MMI is reset to default as designated HW DIP jumper has been switched on.
I2C error (tuner)	4390938	critical	Hardware failure.
I2C error (demodulator)	4390939	critical	Hardware failure.

Error Code	ID	Level	Description
I2C error	4390960	critical	Hardware failure.
Startup Error	4390961	critical	Error during startup.
Card Overheated	4653057	critical	The card temperature is too high. Check the unit and make sure the ventilation vents are positioned correctly.
Card Temperature High	4653058	warning	A warning that the card is on the limit of being too warm.
Dead process	4653059	critical	An internal process is dead. The card will need a reboot. If possible please contact support before reboot.
Message queue not responding	4653060	critical	An internal process is no longer responding. The card will need a reboot. If possible please contact support before reboot.
High CPU load	4653061	warning	The cpu has had less than 5% idle over the last 10 seconds
System low on free memory	4653062	warning	Less than 10% of memory (RAM) is free
System low on free disk space	4653063	critical	Low on free space on mounted file system - more than 90% of storage space is used
Power adapter failure	4653064	critical	One of the two power adapters requires maintenance.
Unit Fan Error	4653065	warning	One or more of the fans needs maintenance. The alarm will specify which one.
Power adapter fan error	4653066	major	Problem with one of the fans in the indicated power adapter.
Fan module not present	4653067	major	The hotswap fan module is currently not detected in the chassis.
Card is not running from the most up-dated (expected) software partition	4653068	critical	The card is not running from the most recently up(down)graded software partition. Possible causes: Multiple power outages during boot, or multiple reboots performed before software is able to start properly.
Power adapter error	4653069	warning	Indicated power adapter is not operating. Possible causes: lost of power cord connection or removal of power adapter.
DNS server not reachable	4653070	critical	The manually configured DNS servers fail to resolve addresses. Reconfigure the DNS servers or disable the manual configuration.
Primary DNS not reachable	4653071	warning	Lookup failure on the primary DNS server. Reconfigure the primary DNS server.
Backup DNS not reachable	4653072	warning	Lookup failure on the backup DNS server. Reconfigure the backup DNS server.
Clock-ref acquiring phase lock	4718594	warning	Coarse tuning is finished and is now in "Fine tuning" mode, acquiring phase lock. SFN outputs are enabled, but holdover functionality is not supported until fully phase locked.
Clock-ref holdover mode	4718595	warning	Lost lock on GPS reference. Danger of losing sync within four hours.
Holdover recovery	4718596	warning	Clock Reference module has been in holdover after losing sync, and is approaching phase lock. SFN outputs are enabled, but holdover functionality is not supported until fully phase locked.
SFN outputs are disabled	4718597	critical	Lost clock sync. SFN outputs will be disabled.



Error Code	ID	Level	Description
SFN signal from clock lost	4718598	critical	The MMI is not receiving the external clock provided by the clock-reference card (it has to be configured to do so: SFN mode), so the whole backplane is muted. Changing the system clock source will restore the functioning of all cards but the ones used for SFN.
Network disk not mounted	5505024	critical	The system has not been able to mount the network disk (NAS). Any transport stream files located on that disk will be unavailable.
File streamer local time out of sync	5505027	warning	File streamer unable to sync to backplane local time (reference clock).
System reference clock not locked to genlock	5832704	critical	The system reference clock has been set up to lock to genlock input, but no frequency locking has been achieved. Either the genlock signal is missing or outside of pull-range of system reference clock
No backplane clock from peer MMI	5832707	warning	The system lost reference clock signal from peer MMI. The system reference clock will go to an internally generated clock

## 25 Upgrade

Error Code	ID	Level	Description
Card setup changes detected: Re-install software to complete	3080298	critical	Some cardsetup changes will require a reinstallation of the software. Typically the system need to re-load a new FPGA image matching the new configuraiton mode.
Scheduler cannot communicate with URL	5111908	major	Check the connection to the ftp server, and verify correct user and password is used. In case where repository FTP address requires name-lookup, verify that a correct DNS server is configured.
Scheduled software upgrade in progress	5111909	critical	A scheduled upgrade is currently installing new software in the unit.
Scheduler configuration file mode insecure	5111910	major	The configuratin file for the scheduler has wrong file mode.
Scheduler cannot read repository manifest	5111911	major	The repository downloaded was not in the correct format. Check the schedulefile references.
Scheduler cannot download repository	5111912	major	The scheduler file points to a file which is not accessible.
Scheduler cannot download external schedule	5111913	major	The scheduler do not find the scheduler file on the ftp server.
Upgrade failed	5111914	major	For some reason an upgrade of a card failed. Check the upgrade log on the ftp server for details.
Upgrade scheduling disabled, NTP time required.	5111915	major	The upgrade scheduler relies on correct time to ensure that the units are upgraded at the time spcified in the schedule file. NTP is therefore a mandatory.
Upgrade scheduler cannot write log to server.	5111916	major	The upgrade scheduler fails uploading the log to the ftp server.